Law Offices

McCarthy, Sweeney & Harkaway, P. C.

1750 Pennsylvania Ave., N. W.

WASHINGTON, D. C. 20006

Telephone (202) 393-5710

Telecopier (202) 393-5721

3-0824055

Andrew P. Goldstein Counsel

CHARLES J. McCarthy

March 23, 1993

Interstate Commerce Commission 18176
12th & Constitution Avenue, N. WRECORDATION NO. FILED 1425
Washington, DC 20423

MAH 2 3 1993 2-2 E PM

Attention:

DOUGLAS M. CANTER

JOHN M. CUTLER, JR. WILLIAM I. HARKAWAY

STEVEN J. KALISH HARVEY L. REITER

DANIEL J. SWEENEY

KATHLEEN L. MAZURE

Mildred Lee

INTERSTATE COMMERCE COMMISSION

Dear Ms. Lee:

Enclosed for filing recordation with the Commission are certified true copy and two counterparts of the document described below to be recorded under Section 11303 of the Interstate Commerce Act, 49 U.S.C. § 11303.

This document is a LEASE, dated November 1, 1992, between Louis Dreyfus Corporation and Northbrook Rail Corporation. This is a primary document.

The names and addresses of the parties to this document are as follows:

Lessor:

Louis Dreyfus Corporation 10 Westport Road Wilton, CT 06895-0810

Lessee:

Northbrook Rail Corporation 2025 South Arlington Heights Road Arlington Heights, IL 60005

Countypas

The equipment covered by this document is two hundred fifty seven (257) covered hopper cars bearing UMP markings.

This document should be indexed as:

Lease Dated November 1, 1992 between Louis Dreyfus Corporation (Lessor) and Northbrook Rail Corporation (Lessee).

This document should be cross-indexed to Nos. 16001, 16002, 16834, and 17419.

Also, enclosed please find a check in the amount of \$16.00 as the filing fee required by 49 C.F.R. 1177.3.

Sincerely,

Andrew P. Goldstein

Attorney for

Louis Dreyfus Corporation

Enclosures

APG/rmm

MAN 2 3 1993 2-25 PM

INTERSTATE COMMERCE COMMISSION

LOUIS DREYFUS CORPORATION LEASE OF COVERED HOPPER CARS

THIS AGREEMENT is made and entered into this 1 st day of November, 1992, by and between LOUIS DREYFUS CORPORATION, a New York Corporation, hereinafter called "LESSOR," and Northbrook Rail Corporation, an Illinois Corporation, hereinafter called "LESSEE."

WITNESSETH:

WHEREAS, LESSOR is willing to lease and LESSEE is desirous leasing the railway covered hopper cars identified in Schedule A hereto, (the "CARS").

NOW THEREFORE, in consideration of the premises and of the covenants, promises, and undertakings of the parties, as hereinafter contained, it is agreed as follows:

SECTION 1. TERM. The term of this AGREEMENT shall be for the period specified in Schedule B hereto. Notwithstanding the actual EFFECTIVE DATE of this AGREEMENT for any of the CARS, this AGREEMENT shall terminate on the date ("TERMINATION DATE") set forth in Schedule B hereto for all CARS subject hereto.

SECTION 2. RENT. LESSEE will pay rent to LESSOR for the use of each of the CARS during the term of this AGREEMENT at the rate per CAR per month set forth in Schedule B hereto, until actual return of the CARS to a point in the Continental United remain on rent for the account of LESSEE until such mark is made Car with suitable for loading. * The per diem rental rate for a CAR for a given month shall be determined by over the number of days in that month. Payments shall be due on the first day of each month for the same month. LESSEE shall maintain or have maintained separate, complete and accurate books and records of mileage and movement relating to the CARS in the same form and to the same extent as customary in the LESSEE'S railcar leasing and management business, and retain such books and records for a period of not less than three (3) years. LESSEE shall make available such books and records for inspection by LESSOR, or its representatives, upon 48 hours prior written notice, during reasonable business hours, and LESSEE shall allow LESSOR, or its representatives to make photocopies thereof at LESSOR'S expense.

SECTION 3. USE. A. Subject to provisions of this AGREE-MENT, LESSEE shall have exclusive use and control of the CARS during the term of this AGREEMENT, or extension thereof, pro-

* LESSEE shall have right to inspect any Car found unsuitable for · loading prior to any repair or cleaning.

vided, however, that said CARS shall be used only within the Continental limits of the United States of America or, on a temporary and incidental basis, in Canada or Mexico; and LESSEE covenants that it does not anticipate that more than 10 percent of the CARS will be in Mexico at any one time.

- LESSEE will preserve the CARS in good condition and will not alter the physical structure of any of the CARS or use the CARS for the transportation of corrosive lading. LESSEE may not change any of the marks, lettering, car initials, or exterior color of the CARS without the prior written permission of LESSOR, and then only on such terms and conditions as LESSOR reasonably may require, including, but not limited to, payment by LESSEE of the costs of making such changes and of returning the CARS to the exterior condition that they were in prior to making any such changes. Notwithstanding this Section 3B, LESSEE may change the marks on the CARS from "LDCX" to "UMP" and shall remark each of the CARS in such manner as LESSOR directs before the last loaded move of that CAR under this LEASE. LESSEE shall maintain in contrasting color the plate or stencil that is on each of the CARS that states "OWNED BY A LESSOR AND SUBJECT TO AN EQUIPMENT LEASE FILED UNDER THE INTERSTATE COMMERCE ACT, SECTION 11303". LESSEE shall notify LESSOR in writing of each change of any of the marks or any stencil on any of the CARS. When LESSEE remarks LESSOR'S marks, LESSOR will reimburse LESSEE for each of the CARS the lesser of (i) \$50.00 or (ii) half of LESSEE'S cost of that remarking. When LESSEE remarks CARS in accordance to LESSOR'S direction, LESSOR will reimburse LESSEE the lesser of (i) \$100.00 or (ii) half of LESSEE'S cost of that remarking.
- C. LESSEE shall use the CARS upon each railroad over which the CARS shall move in accordance with all governmental rules and regulations, interchange rules of the Association of American Railroads ("AAR"), and then prevailing tariffs and other applicable rules and regulations to which each said railroad shall be a party; and if the operation or movement of any of the CARS during the term of this AGREEMENT shall result in charges being made against the LESSOR by any railroad or association, LESSEE shall pay LESSOR for such charges within ten (10) days of receiving notice that such charges are due.
- D. LESSEE shall be liable for any demurrage, track storage, or detention charge imposed in connection with any of the Cars as well as loss of or damage to any CAR while on any private siding or track or on any private or industrial railroad or in the custody of any carrier not subject to the Association of American Railroads Rules for Interchange.

SECTION 4. <u>MAINTENANCE</u>. A. LESSOR shall be responsible for the cost of maintaining the CARS with the exception of the following:

LESSEE shall be responsible for the payment of all costs of repairs if any of said CARS are damaged due to use of the CARS in a manner other than that for which they were designed or due to the carrying of corrosive or abrasive materials, spilling of damaging materials, or the carrying of any material or performing any act which would damage a CAR or any part of it.

- B. LESSEE at its own expense, shall either replace or reimburse Lessor for the cost of replacing any appliance or removable part, including, but not limited to hatch covers and gates, if destroyed, damaged, lost, removed, or stolen, unless the railroads transporting the CARS have assumed full responsibility for such loss or damages, or unless such loss or damage results from the negligence or omission of LESSOR, its agents or employees.
- C. The LESSEE will cause the CARS or any of them, when in need of repair or maintenance, to be delivered to a mutually agreeable repair shop without cost to LESSOR, and to accept delivery of the CARS at that point when the repairs have been made. On any CAR needing such maintenance, rental shall abate five (5) days after the CAR is received in LESSOR'S designated shop, and until CAR is shipped from LESSOR'S designated shop. On any CAR repaired without prior notice by LESSEE to LESSOR or for LESSEE responsible repairs, rental will not abate.
- D. LESSOR shall have the right by its authorized representatives to inspect the CARS at the sole cost and expense of LESSOR at such times as LESSOR deems necessary and LESSEE will cooperate with LESSOR in making the CARS available for such inspections upon reasonable notice and request at a limited number of locations and in reasonable quantities.
- E. LESSEE shall not modify any of the CARS without LESSOR'S approval.

SECTION 5. <u>DAMAGE OR DESTRUCTION</u>. LESSEE promptly shall notify LESSOR of any damage to or destruction of the CARS. In the event any CAR is lost due to destruction or damage beyond economical repair in the sole judgment of LESSOR, LESSOR shall be entitled to all compensation by the responsible party for the loss of the CAR in accordance with applicable AAR Rules or otherwise. Upon confirmation that any CAR has been lost due to destruction or damage beyond economic repair, rental charges shall be abated and LESSOR shall issue credits to LESSEE for any and all rental payments made after the date of said destruction or damage. LESSOR, at its option, may or may not replace such destroyed or damaged CARS with cars of comparable size, and capacity, which, if so replaced, shall then be deemed a CAR subject to this AGREEMENT. The rental for such replacement CAR


and same UMLER values,

shall commence to accrue on the date of arrival of the replacement CAR at a point mutually agreed upon by LESSOR and LESSEE.

SECTION 6. <u>LIABILITY</u>. Except for acts of negligence attributable solely to LESSOR or its Agents, LESSOR shall not be liable for (a) any loss of, or damage to, commodities or property, or any part thereof, loaded or shipped in the CARS, however such loss or damage may be caused or result, or (b) any loss or damage arising through injury to or death of persons or damage to any other property, however such loss or damage may be caused or result. LESSEE assumes responsibility for and agrees to indemnify LESSOR against the cost of defending any claims made against LESSOR and any judgments rendered against LESSOR for the events and occurrences described in this paragraph.

SECTION 7. TAXES. LESSOR shall pay all property taxes properly imposed or measured by such CARS on the mileage thereon, and will file all property tax reports relating thereto. LESSEE shall be responsible for and will indemnify LESSOR from all sales and/or use taxes, duties, and tariffs imposed by federal, state, municipal, and other governmental authority. LESSEE agrees to cooperate fully and promptly with LESSOR in providing to LESSOR any information which LESSOR may deem necessary to fulfillment of its obligations under this paragraph.

SECTION 8. DELIVERY OF CARS UPON TERMINATION. TERMINATION DATE or upon failure of LESSEE to cure the breach of any conditions or covenant herein by it within ten (10) days after written notice thereof by LESSOR to LESSEE, LESSEE shall deliver the CARS * free and clear of any and all transportation charges, to LESSOR at the point or points in the Continental United States designated by LESSOR. If LESSEE shall fail or refuse to deliver said CARS as aforesaid, LESSOR shall have the right, without further notice or demand, and in addition to and without constituting a waiver of any other remedy, claim or right hereunder or at law to: (i) if this AGREEMENT is terminated in accordance with provisions hereof, to take possession of said CARS wherever found, or (ii) either to take possession of said CARS wherever found without terminating this AGREEMENT, or to terminate this AGREEMENT and to take possession of said CARS wherever found, and in all cases with or without legal process, and remove them at LESSEE's expense, and for such purpose LESSEE authorizes LESSOR to enter any premises occupied by LESSEE or to issue such CAR relocation directives to railroads who may be in possession of the CARS. LESSEE agrees to indemnify and pay to the LESSOR reasonable attorney's fees and costs of repossession. Provided further that unless LESSEE delivers more than 90% of the CARS to a point designated by LESSOR (within the Continental United States) within 30 days after the termination date of the AGREEMENT, LESSOR shall have the right to impose on LESSEE a rental surcharge equal to twice the monthly rate, pro-rata for the number of days from (and including) the 30th day after the last day of the AGREEMENT to



(but excluding) the date LESSEE delivers a CAR or CARS to LESSOR'S designated point.

Photo Like

SECTION 9. <u>SUCCESSORS AND ASSIGNMENT</u>. This AGREEMENT and the terms and provisions and covenants herein contained shall extend to and be binding upon and shall inure to the benefit of the respective successors and assigns of the respective parties hereto. LESSOR recognizes that it is the intention of LESSEE to sublease the CARS to third parties without further notice to LESSOR. Notwithstanding any sublease, LESSEE shall continue to remain liable to LESSOR under all terms and conditions of this AGREEMENT. LESSEE, however, shall not otherwise encumber their leasehold interest in any of the CARS or assign or use this AGREEMENT as security, without prior written consent of LESSOR.

pur

SECTION 10. <u>INSURANCE</u>. LESSEE will, at all times prior to the return of the CARS to LESSOR, at LESSEE's own expense, cause to be carried and maintained public liability insurance in respect to the CARS against risks customarily insured against by LESSEE in respect of similar equipment owned or leased by LESSEE, but in any event consistent with prudent industry standards. The public liability insurance to be carried and maintained hereunder shall be in an amount not less than Three Million and NO/100 Dollars (\$3,000,000.00), with a deductible amount not greater than Fifty Thousand and No/100 Dollars (\$50,000.00) per each occurrence.

SECTION 11. ENTIRE AGREEMENT. This instrument, including all Schedules and Riders hereto, contains the entire agreement of the parties. It may not be changed orally, but only by an agreement in writing signed by the party against whom enforcement or any waiver, change, modification, extension or discharge is sought.

SECTION 12. <u>WAIVER</u>. A waiver of a breach of any of the conditions, covenants or agreements in this lease by any party shall not be construed to be a waiver of any subsequent breach of any such conditions, covenant or other agreement.

SECTION 13. GOVERNING LAW. This AGREEMENT shall be subject to the laws of New York applicable to contracts to be performed entirely within that state.

SECTION 14. GENERAL. Sections 3B, 5, 6, and 7 shall survive the termination of this LEASE and the return of the CARS.

SECTION 15. <u>NOTICES</u>. Any notices required or made hereunder in writing shall be provided by certified mail, return receipt requested, to:

For LESSOR: Louis Dreyfus Corporation

10 Westport Road, P. O. Box 810

Wilton, CT 06897-0810

ATTENTION: Lawrence J. Greenhall

For LESSEE: Northbrook Rail Corporation

2025 South Arlington Heights Road, Suite 119

Arlington Heights, Illinois 60005

ATTENTION: Executive Vice President

IN WITNESS WHEREOF, LESSOR and LESSEE respectively, each pursuant to due corporate authority, have caused these presents to be executed and their respective corporate seals to be here onto affixed duly attested, as of the day and year first above written.

(CORPORAT	Έ	SEAL)
ATTEST:		

(LESSEE)

By: Carmen Palka

Date: 1-15-93

(CORPORATE SEAL)
ATTEST: / /

By:

Date: 2-1-93

Northbrook

Rail

Corporation

By:

LOUIS DREYFUS CORPORATION (LESSOR)

Bv:

Lawrence J. Greenhall

Vice President

SCHEDULE A

Page 1 of Schedule A to Lease Agreement dated November 1, 1992 by and between LOUIS DREYFUS CORPORATION (LESSOR) and NORTHBROOK RAIL CORPORATION (LESSEE).

TYPE AND DESCRIPTION OF CARS: 4750 cu. ft. 100-ton Covered Hopper Cars, equipped with trough hatches and gravity outlets

NUMBER OF CARS: 250 257

INTERIOR EQUIPMENT: None

SPECIAL LININGS: None

PERMITTED LADING USE: Grain and Grain Products

REPORTING MARKS AND NUMBERS: as listed on the following pages of Schedule A

(CORPORATE SEAL)

ATTEST:

NORTHBROOK RAIL CORPORATION

(LESSEE)

By: Carmen Paera

Bv:

Date: 1-15-93

(CORPORATE SEAL)

ATTEST:

By:

Date: 2-1-93

LOUIS DREYFUS CORPORATION (LESSOR)

By:

Lavrence J. Greenhall

Vide President

LISTING OF CARS FOR SCHEDULE A

UMP 020319 UMP 020756 UMP 02084 UMP 020327 UMP 020757 UMP 02085 UMP 020426 UMP 020758 UMP 02085 UMP 020440 UMP 020759 UMP 02085 UMP 020442 UMP 020760 UMP 02085 UMP 020462 UMP 020761 UMP 02085 UMP 020464 UMP 020762 UMP 02088 UMP 020483 UMP 020763 UMP 02088 UMP 020504 UMP 020765 UMP 02088 UMP 020526 UMP 020765 UMP 02096 UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020560 UMP 020771 UMP 02100 UMP 020564	7
UMP 020426 UMP 020758 UMP 02085 UMP 020440 UMP 020759 UMP 02085 UMP 020442 UMP 020760 UMP 02085 UMP 020462 UMP 020761 UMP 02085 UMP 020464 UMP 020762 UMP 02088 UMP 020483 UMP 020763 UMP 02088 UMP 020504 UMP 020764 UMP 02088 UMP 020526 UMP 020765 UMP 02096 UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02098 UMP 020544 UMP 020769 UMP 02098 UMP 020556 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	8
UMP 020440 UMP 020759 UMP 02085 UMP 020442 UMP 020760 UMP 02085 UMP 020462 UMP 020761 UMP 02085 UMP 020464 UMP 020762 UMP 02088 UMP 020483 UMP 020763 UMP 02088 UMP 020504 UMP 020764 UMP 02088 UMP 020526 UMP 020765 UMP 02096 UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02098 UMP 020544 UMP 020769 UMP 02098 UMP 020556 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	0
UMP 020442 UMP 020760 UMP 02085 UMP 020462 UMP 020761 UMP 02085 UMP 020464 UMP 020762 UMP 02088 UMP 020483 UMP 020763 UMP 02088 UMP 020504 UMP 020764 UMP 02088 UMP 020526 UMP 020765 UMP 02096 UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	1
UMP 020462 UMP 020761 UMP 02085 UMP 020464 UMP 020762 UMP 02088 UMP 020483 UMP 020763 UMP 02088 UMP 020504 UMP 020764 UMP 02088 UMP 020526 UMP 020765 UMP 02096 UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	2
UMP 020464 UMP 020762 UMP 02088 UMP 020483 UMP 020763 UMP 02088 UMP 020504 UMP 020764 UMP 02088 UMP 020526 UMP 020765 UMP 02096 UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	6
UMP 020483 UMP 020763 UMP 02088 UMP 020504 UMP 020764 UMP 02088 UMP 020526 UMP 020765 UMP 02096 UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	7
UMP 020504 UMP 020764 UMP 02088 UMP 020526 UMP 020765 UMP 02096 UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	1
UMP 020526 UMP 020765 UMP 02096 UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	7
UMP 020527 UMP 020766 UMP 02097 UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	8
UMP 020534 UMP 020767 UMP 02097 UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	7
UMP 020544 UMP 020768 UMP 02098 UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	0
UMP 020556 UMP 020769 UMP 02098 UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	9
UMP 020557 UMP 020770 UMP 02100 UMP 020560 UMP 020771 UMP 02100	6
UMP 020560 UMP 020771 UMP 02100	9
•	0
TIMD 020564 TIMD 020772 TIMD 02101	13
OHI 020304 OHI 020772 OHI 02101	8.
UMP 020586 UMP 020773 UMP 02102	2
UMP 020595 UMP 020774 UMP 02103	4
UMP 020596 UMP 020775 UMP 02104	5
UMP 020598 UMP 020776 UMP 02120	1
UMP 020600 UMP 020777 UMP 02120	5
UMP 020601 UMP 020778 UMP 02120	6
UMP 020602 UMP 020779 UMP 02121	.1
UMP 020603 UMP 020780 UMP 02121	.2
UMP 020606 UMP 020781 UMP 02121	.5
UMP 020608 UMP 020782 UMP 02121	.9
UMP 020609 UMP 020783 UMP 02122	1
UMP 020611 UMP 020784 UMP 02122	3
UMP 020612 UMP 020785 UMP 02122	6
UMP 020615 UMP 020786 UMP 02122	8
UMP 020631 UMP 020787 UMP 02123	1
UMP 020636 UMP 020788 UMP 02123	
UMP 020644 UMP 020789 UMP 02123	4
UMP 020653 UMP 020792 UMP 02123	6
UMP 020654 UMP 020793 UMP 02123	
UMP 020666 UMP 020794 UMP 02123	8
UMP 020671 UMP 020795 UMP 02124	3
UMP 020675 UMP 020796 UMP 02124	4
UMP 020676 UMP 020797 UMP 02124	.5
UMP 020692 UMP 020798 UMP 02124	
UMP 020695 UMP 020799 UMP 02125	
UMP 020697 UMP 020800 UMP 02125	
UMP 020700 UMP 020801 UMP 02125	
UMP 020710 UMP 020802 UMP 02125	
UMP 020712 UMP 020803 UMP 02126	
UMP 020713 UMP 020804 UMP 02126	

UMP 020714 UMP 020805 UMP 020715 UMP 020806 UMP 020716 UMP 020807 UMP 020717 UMP 020808 UMP 020718 UMP 020809 UMP 020719 UMP 020810 UMP 020720 UMP 020811 UMP 020721 UMP 020815 UMP 020722 UMP 020815 UMP 020723 UMP 020816 UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020726 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020820 UMP 020730 UMP 020820 UMP 020730 UMP 020821 UMP 020731 UMP 020823 UMP 020731 UMP 020824 UMP 020732 UMP 020825 UMP 020731 UMP 020825 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020734 UMP 020826 UMP 020735 UMP 020827 UMP 020736 UMP 020827 UMP 020736 UMP 020827 UMP 020737 UMP 020827 UMP 020738 UMP 020828 UMP 020738 UMP 020829 UMP 020739 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020832 UMP 020740 UMP 020832 UMP 020741 UMP 020834 UMP 020745 UMP 020837 UMP 020745 UMP 020837 UMP 020745 UMP 020837 UMP 020746 UMP 020839 UMP 020747 UMP 020839 UMP 020749 UMP 020844 UMP 020750 UMP 020843 UMP 020750 UMP 020843 UMP 020751 UMP 020844	
UMP 020715 UMP 020806 UMP 020717 UMP 020807 UMP 020718 UMP 020809 UMP 020719 UMP 020810 UMP 020720 UMP 020811 UMP 020721 UMP 020815 UMP 020722 UMP 020815 UMP 020723 UMP 020816 UMP 020724 UMP 020725 UMP 020817 UMP 020725 UMP 020817 UMP 020726 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020820 UMP 020730 UMP 020821 UMP 020731 UMP 020821 UMP 020731 UMP 020825 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020825 UMP 020734 UMP 020735 UMP 020825 UMP 020736 UMP 020827 UMP 020736 UMP 020828 UMP 020737 UMP 020829 UMP 020738 UMP 020829 UMP 020739 UMP 020831 UMP 020833 UMP 020833 UMP 020833 UMP 020833 UMP 020833 UMP 020833 UMP 020834 UMP 020740 UMP 020836 UMP 020837 UMP 020837 UMP 020839 UMP 020840 UMP 020749 UMP 020844	
UMP 020716 UMP 020717 UMP 020808 UMP 020718 UMP 020809 UMP 020719 UMP 020810 UMP 020720 UMP 020811 UMP 020721 UMP 020815 UMP 020721 UMP 020815 UMP 020723 UMP 020816 UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020725 UMP 020819 UMP 020726 UMP 020819 UMP 020728 UMP 020819 UMP 020728 UMP 020820 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020731 UMP 020732 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020825 UMP 020734 UMP 020735 UMP 020827 UMP 020735 UMP 020827 UMP 020736 UMP 020828 UMP 020737 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020829 UMP 020738 UMP 020830 UMP 020831 UMP 020739 UMP 020831 UMP 020831 UMP 020740 UMP 020831 UMP 020831 UMP 020744 UMP 020833 UMP 020831 UMP 020831 UMP 020833 UMP 020833 UMP 020833 UMP 020834 UMP 020834 UMP 020834 UMP 020834 UMP 020834 UMP 020744 UMP 020839 UMP 020849 UMP 020840 UMP 020750 UMP 020844 UMP 020844 UMP 020844 UMP 020844	UMP 021271
UMP 020717 UMP 020808 UMP 020718 UMP 020809 UMP 020719 UMP 020810 UMP 020720 UMP 020811 UMP 020721 UMP 020815 UMP 020722 UMP 020815 UMP 020723 UMP 020816 UMP 020725 UMP 020818 UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020820 UMP 020730 UMP 020821 UMP 020731 UMP 020823 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020825 UMP 020734 UMP 020825 UMP 020735 UMP 020826 UMP 020736 UMP 020827 UMP 020736 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020829 UMP 020738 UMP 020829 UMP 020738 UMP 020830 UMP 020739 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020832 UMP 020740 UMP 020834 UMP 020741 UMP 020835 UMP 020741 UMP 020835 UMP 020741 UMP 020836 UMP 020745 UMP 020836 UMP 020746 UMP 020839 UMP 020747 UMP 020839 UMP 020749 UMP 020842 UMP 020750 UMP 020844 UMP 020751 UMP 020844 UMP 020751 UMP 020845	UMP 021272
UMP 020718 UMP 020809 UMP 020719 UMP 020810 UMP 020720 UMP 020811 UMP 020721 UMP 020812 UMP 020722 UMP 020815 UMP 020723 UMP 020816 UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020821 UMP 020731 UMP 020824 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020733 UMP 020825 UMP 020734 UMP 020825 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020828 UMP 020738 UMP 020829 UMP 020738 UMP 020830 UMP 020739 UMP 020830 UMP 020739 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020831 UMP 020740 UMP 020835 UMP 020741 UMP 020835 UMP 020741 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020837 UMP 020747 UMP 020839 UMP 020748 UMP 020839 UMP 020749 UMP 020844 UMP 020750 UMP 020843 UMP 020750 UMP 020844 UMP 020751 UMP 020845	UMP 021273
UMP 020719 UMP 020810 UMP 020720 UMP 020811 UMP 020721 UMP 020812 UMP 020722 UMP 020815 UMP 020723 UMP 020816 UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020824 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020827 UMP 020736 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020829 UMP 020738 UMP 020831 UMP 020738 UMP 020831 UMP 020739 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020833 UMP 020740 UMP 020834 UMP 020741 UMP 020835 UMP 020740 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020837 UMP 020746 UMP 020837 UMP 020747 UMP 020839 UMP 020748 UMP 020849 UMP 020749 UMP 020844 UMP 020750 UMP 020844 UMP 020751 UMP 020844	UMP 021274
UMP 020720 UMP 020811 UMP 020721 UMP 020812 UMP 020722 UMP 020815 UMP 020723 UMP 020816 UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020824 UMP 020731 UMP 020825 UMP 020733 UMP 020825 UMP 020733 UMP 020825 UMP 020734 UMP 020826 UMP 020735 UMP 020828 UMP 020736 UMP 020828 UMP 020737 UMP 020828 UMP 020737 UMP 020829 UMP 020738 UMP 020829 UMP 020739 UMP 020830 UMP 020739 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020832 UMP 020741 UMP 020833 UMP 020741 UMP 020835 UMP 020744 UMP 020835 UMP 020745 UMP 020835 UMP 020745 UMP 020837 UMP 020746 UMP 020837 UMP 020746 UMP 020839 UMP 020747 UMP 020839 UMP 020748 UMP 020839 UMP 020749 UMP 020844 UMP 020750 UMP 020844 UMP 020750 UMP 020844 UMP 020751 UMP 020844	UMP 021277
UMP 020721 UMP 020812 UMP 020722 UMP 020815 UMP 020723 UMP 020816 UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020824 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020825 UMP 020734 UMP 020827 UMP 020735 UMP 020827 UMP 020736 UMP 020828 UMP 020737 UMP 020829 UMP 020738 UMP 020829 UMP 020738 UMP 020830 UMP 020739 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020833 UMP 020741 UMP 020835 UMP 020741 UMP 020835 UMP 020745 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020837 UMP 020746 UMP 020839 UMP 020747 UMP 020839 UMP 020748 UMP 020839 UMP 020749 UMP 020842 UMP 020749 UMP 020844 UMP 020750 UMP 020844 UMP 020751 UMP 020844	UMP 021278
UMP 020722 UMP 020815 UMP 020723 UMP 020816 UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020824 UMP 020731 UMP 020825 UMP 020733 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020827 UMP 020736 UMP 020828 UMP 020737 UMP 020829 UMP 020738 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020832 UMP 020740 UMP 020835 UMP 020741 UMP 020835 UMP 020741 UMP 020836 UMP 020745 UMP 020836 UMP 020746 UMP 020837 UMP 020746 UMP 020837 UMP 020746 UMP 020839 UMP 020747 UMP 020839 UMP 020748 UMP 020839 UMP 020749 UMP 020840 UMP 020750 UMP 020844 UMP 020751 UMP 020844 UMP 020751 UMP 020844	UMP 021279
UMP 020723 UMP 020816 UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020828 UMP 020737 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020744 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020836 UMP 020746 UMP 020837 UMP 020746 UMP 020837 UMP 020747 UMP 020839 UMP 020748 UMP 020839 UMP 020749 UMP 020840 UMP 020750 UMP 020844 UMP 020751 UMP 020844	UMP 021281
UMP 020724 UMP 020817 UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020828 UMP 020737 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020738 UMP 020831 UMP 020740 UMP 020833 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020744 UMP 020835 UMP 020745 UMP 020835 UMP 020746 UMP 020837 UMP 020746 UMP 020837 UMP 020747 UMP 020838 UMP 020748 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020843 UMP 020750 UMP 020844 UMP 020751 UMP 020844 UMP 020751 UMP 020845	UMP 021285
UMP 020725 UMP 020818 UMP 020726 UMP 020819 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020832 UMP 020741 UMP 020833 UMP 020741 UMP 020835 UMP 020744 UMP 020835 UMP 020745 UMP 020836 UMP 020746 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020839 UMP 020749 UMP 020844 UMP 020750 UMP 020843 UMP 020751 UMP 020845	UMP 021289
UMP 020726 UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020825 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020735 UMP 020828 UMP 020737 UMP 020737 UMP 020829 UMP 020738 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020833 UMP 020741 UMP 020741 UMP 020835 UMP 020742 UMP 020744 UMP 020836 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020839 UMP 020746 UMP 020839 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020843 UMP 020843 UMP 020750 UMP 020844 UMP 020844	UMP 021294
UMP 020728 UMP 020820 UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020824 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020833 UMP 020741 UMP 020835 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020844 UMP 020751 UMP 020844 UMP 020751 UMP 020845	UMP 021295
UMP 020729 UMP 020821 UMP 020730 UMP 020823 UMP 020731 UMP 020824 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020741 UMP 020835 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020751 UMP 020844	UMP 021297
UMP 020730 UMP 020823 UMP 020731 UMP 020824 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020831 UMP 020740 UMP 020833 UMP 020741 UMP 020833 UMP 020741 UMP 020835 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020843 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020751 UMP 020844	UMP 021305
UMP 020731 UMP 020824 UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020741 UMP 020835 UMP 020744 UMP 020835 UMP 020745 UMP 020836 UMP 020746 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020751 UMP 020844 UMP 020751 UMP 020845	UMP 021308
UMP 020732 UMP 020825 UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020844 UMP 020751 UMP 020844 UMP 020751 UMP 020845	UMP 021314
UMP 020733 UMP 020826 UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020741 UMP 020835 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020751 UMP 020844	UMP 021315
UMP 020734 UMP 020827 UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020741 UMP 020835 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020844	UMP 021316
UMP 020735 UMP 020828 UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020838 UMP 020748 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020844 UMP 020844 UMP 020844	UMP 021319
UMP 020736 UMP 020829 UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020844 UMP 020844 UMP 020845	UMP 021327
UMP 020737 UMP 020830 UMP 020738 UMP 020831 UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020845	UMP 021334
UMP 020738 UMP 020831 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020745 UMP 020746 UMP 020746 UMP 020747 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020845	UMP 021336
UMP 020739 UMP 020832 UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 021338
UMP 020740 UMP 020833 UMP 020741 UMP 020834 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 021341
UMP 020741 UMP 020834 UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120227
UMP 020742 UMP 020835 UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120404
UMP 020744 UMP 020836 UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120450
UMP 020745 UMP 020837 UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120467
UMP 020746 UMP 020838 UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120473
UMP 020747 UMP 020839 UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120500
UMP 020748 UMP 020840 UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120521
UMP 020749 UMP 020842 UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120533
UMP 020750 UMP 020843 UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120565
UMP 020751 UMP 020844 UMP 020752 UMP 020845	UMP 120597
UMP 020752 UMP 020845	UMP 120599
	UMP 120640
	UMP 120673
UMP 020753 UMP 020846	

CERTIFICATE

I, Andrew P. Goldstein, hereby certify that I am an attorney duly admitted in the District of Columbia, and am a member in good standing of the Bar of the District of Columbia, and that I have, this 23rd day of March, 1993, compared the enclosed copy of a certain Lease of Covered Hopper Cars, dated November 1, 1992, between Louis Dreyfus Corporation, Lessor, and Northbrook Rail Corporation, Lessee, with the original document, and certify that it is complete and identical in all respects to the original document and Schedule A thereto.

Andrew P. Goldstein

Sworn to and subscribed before me this 23rd day of March, 1993.

Notary Public

My commission expires on March 14, 1998.